

PURCHASE ORDER

PROVINCIAL GOVERNMENT OF CAMARINES NORTE

Supplier : **BACERDO AUTO REPAIR SHOP** P.O. No. : **23071979**
Address : Purok 2 Brgy. Magang Daet, Camarines Norte Date : **09-19-23**
Telephone No. : 0946-542-8455 Mode of Procurement : **SVP**
TIN : 925-522-427-000

Gentlemen:

Please furnish this office the following articles subject to the terms and conditions contained herein:

Place of Delivery: **GO (USSAP)-(SWAK)** Delivery Term : 700
Date of Delivery : 09/27/23 Payment Term: FULL


| Item No. | Quantity | Unit Issue | ITEM DESCRIPTION | Amount | |
|----------|----------|------------|---|-----------|------------|
| | | | | Unit Cost | Total Cost |
| 1 | 1 | pc | Wiper motor assy | 3,350.00 | 3,350.00 |
| 2 | 2 | pc | Wiper Blade | 395.00 | 790.00 |
| 3 | 1 | pc | Released Bearing | 1,355.00 | 1,355.00 |
| 4 | 1 | pc | Clutch Disc | 3,825.00 | 3,825.00 |
| 5 | 1 | pc | Pressure Plate | 4,385.00 | 4,385.00 |
| 6 | 4 | pc | Tires (6 Fly) | 6,300.00 | 25,200.00 |
| 7 | 1 | LS | Labor fee: <i>Stepboard Welding Clutch leak and replaces Replaced wiper motor Replaced wiper blade Replaced pressure plate Replaced released bearing</i> | 7,800.00 | 7,800.00 |

for Governor's Office-USSAP use

Total amount in words: **Forty Six Thousand Seven Hundred Five Pesos Only** **46,705.00**

In case of failure to deliver within the time specified above, penalty of one-tenth (1/10) of one (1) percent of every day of delay shall be imposed.

Very truly yours,

Conforme: 
JOVERT A. BACERDO
Signature over printed name of Supplier
09-20-23
Date

RICARTE R. PADILLA
Governor

